ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
8

Ward Name
Kodigehalli

Street ID
W0266, W0339, W0262, W0327, W0264, W0357

Street Name
NA, Ambedkar Nagar Slum, Lakshmi Sagar Lyt North Side, 2nd Crs, Mariyappa Lyt

Significant Landmark
Hosahalli and Sonnegowda layout surrounding

Segment No.
8/C-W0266/S030925

Total Length (m)
335.14

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	93.23	77.578769	13.058803	77.579564	13.058482	W0327	W0339
2	81.45	77.578874	13.059055	77.579575	13.058790	W0327	DEAD END
3	160.46	77.578921	13.059330	77.578367	13.057985	RI-A23	W0339

Work Details

History of Road / Lane / Circles

Name of the Work
Improvements to Roads and Drain at Hosahalli and Sonnegowda layout surrounding inward no 08 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
2000000

Sanctioned Year
2015

Year
2015 - 2016

Type of Work
Asphalting

Other Work Type

Tender
Tender

Work Details
Improvements to Roads and Drain at Hosahalli and Sonnegowda layout surrounding inward no 08 (Kodigehalli) Kodigehalli Sub-Division Yelahanka zone

Job No. / Work Code
008-16-000006

Work Order No.
EE/BTP/BBMP/E-PMT/225/2015-16

Work Order Date
26/02/2016

Period of Extention
90 DAYS

Defect Liability Period From
26/02/2016

Defect Liability Period To
25/02/2017

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
N.NARASIMHAIAH		0.00

Phone No.	E-Mail ID
9343197369	

Field Inspection Details

Number of Trees	Any Other Information	Name
9		SRINIVASA MURTHY
Date of Inspection	**Remarks**	
25/07/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0266, W0339, W0262, W0327,

Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.
Road Condition		This photo seems out of range.

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0266, W0339, W0262, W0327,

Road Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	25/07/2016	24/08/2016	COMPLETED
SE	VASU K M	25/07/2016	24/08/2016	COMPLETED
EE	YARAPPA REDDY	25/07/2016	24/08/2016	COMPLETED
AEE	RAJANIKANTH	25/07/2016	24/08/2016	COMPLETED
AE	SRINIVASA MURTHY	25/07/2016	24/08/2016	COMPLETED
AE	SRINIVASA MURTHY	25/07/2016	24/08/2016	COMPLETED

Zone: YELAHANKA **Ward No:** 8 **Ward Name:** Kodigehalli **Street ID:** W0266, W0339, W0262, W0327,